	OTHR	
	· · · · · · · · · · · · · · · · · · ·	
	4 January 1964	
	Dear Ray: STATOTHR	
	As indicated by in a telephone conversation on 31 December 1963, we are sending to Mr a letter, a copy of which is enclosed, in which we set forth questions concerning the interconnections between the	
STATO	plotter and the computer. STATOTHR  STATOT	HR
	Note that we are proceeding on the assumption that the dividing line between the and the plotter will be at the output of the cable in the plotter room. With this arrangement, only equipment and no plotter equipment will be located in the computer room and only plotter equipment will be located in the plotter room. We highly recommend this approach. Therefore, we would request that you initiate whatever coordinating action	STATOTH
ATOTHR	is required withthrough your resident technical representative.  STATOTHR In addition, note that in our enclosed letter (paragraph 8), we have requested	
	copies of schematic diagrams pertinent to output and input amplifiers.  Since, quite obviously, you are a good customer of and undoubtedly are paying a goodly rental fee, you should be in a strong position to obtain these schematics for us. We would appreciate it if you would	STATOTI
	assist us in obtaining them. STATOTHR	
	JTB:P	
	Enclosure Staff Engineer	

Declass Review, NIMA/DoD